

**Table 2 - General Problems (not location specific)**

Item #	Description
1	Numerous docks are listing due to unbalanced flotation beneath. This can be particularly dangerous in colder months when frost or ice forms on docks.
2	Many slips which are too short for boat sizes, making boarding/docking hazardous
3	Many electrical boxes have non-functional sockets
4	Insufficient electrical supply to many dock electrical boxes
5	Inadequate security
6	Improved lighting, docks are poorly lit. This is a safety concern, particularly in winter with longer hours of darkness and slippery docks
7	Many dinghy docks are severely listing & unusable or unsafe.
8	Not enough dinghy docks to supply patrons needs for dinghy storage.
9	Wi-fi reception is nonexistent
10	Recycling of oil/etc is located too far from main area of marina
11	Lack of sufficient staff to perform maintenance duties
12	Lack of regular cleaning of goose / otter waste from docs.
13	Lack of winter water supply for flushing outboard motors. One owner reports it cost over \$400 to replace a salt-plugged cooling water pipe three years ago, now the driveshaft is seized and may not be repairable. New motor may cost thousands.